

3F, Building Block 2, No. 3400 Gonghexin Road, Jing'an District - Shanghai 200436, P.R. CHINA 上海市静安区共和新路3400号2幢3层

Tél.: +86 21 68 55 50 32 Fax: +86 21 68 55 50 33 E-mail: ctcshanghai@ctcgroupe.com

huangcongmin@intco.com

## TEST REPORT

Page 1/3

Report No.: S210706718\_2

06 September 2021

APPLICANT: ANHUI INTCO MEDICAL PRODUCTS CO.LTD 安

徽英科医疗用品有限公司(C41483)

安徽省濉溪县濉溪芜湖现代产业园海棠南

路6号

No. 6, Haitang South Road, Suixi Wuhu Modern Industrial Park, Suixi County

. HUAIBEI ANHUI

CHINA

Date of receipt :16 July 2021 :19 July 2021 Testing period

:22 July 2021

Disposable Nitrile Gloves (NBR) 7S, 8M, 9L, 10XL Sample description:

Order no. :YL216227

Buyer: --

Test(s) requested

Service : REGULAR Brand / Section

Season End use

Factory name Factory code

Revision :Amend sample information. For CE Marking: Yes

Previous report Product category

Product type :FIRST TEST Test stage

Supplier name Exported to

### 1. Conclusion:

	<u>Tests description</u>	Conformity
	EN ISO 374-1	
1	Air Leak Test	Pass
2	Water Leak Test	Pass

Pass: requirements met Fail: requirements not met None: no requirement for this test N/A: not applicable

Approved by

Henry YAN 严滨 Laboratory Manager

This test report in version S210706718\_2 supersedes the report S210706718\_1



# **TEST REPORT**

Page 2/3

Report No.: S210706718\_2 06 September 2021

APPLICANT: ANHUI INTCO MEDICAL PRODUCTS CO. LTD 安

徽英科医疗用品有限公司 (C41483)

### 2. Sample(s) description assigned by laboratory:

Size	Analyzed product	<u>Description</u>	Sample information
	GLOVE		
		Whole glove	7S,8M,9L,10XL















210706718-4



## **TEST REPORT**

Page 3/3

Report No.: S210706718\_2 06 September 2021

APPLICANT: ANHUI INTCO MEDICAL PRODUCTS CO.LTD 安

徽英科医疗用品有限公司(C41483)

#### 3. GLOVE/

Whole glove: 7S, 8M, 9L, 10XL

	Method	Client Requirement	Unit	Result	Conformity
• 5.2. Air Leak Test	EN ISO 374-2:2019				Pass
Glove thickness			mm	0.06	
Air pressure used to test			kPa	2.3	
Result		No air bubbles		No air bubbles	
• 5.2. Water Leak Test	EN ISO 374-2:2019				Pass
Result		No water leak		No water leak	

#### **END OF TEST REPORT**

•: The test was carried out by external accredited laboratory, not within their accreditation scope.